
FP52I06 FLOOR PAN TECH BULLETIN



Note: The manufactory's protective device located between the front seats should not be altered. As a result of this, and the different aftermarket console lengths, the Pro-gard floor pan (FP52I06) will have to be altered. See the following photo for reference only.

If you have questions concerning the floor pan installation, please contact Pro-gard technical support department @ 317-579-6680.



P:\Archived Instructions\PF52I06 TECH BULLETIN.doc

REVISION 1: 8/16/2006